


MCS Flexible Transactional System



MSE Power Requirements:

- 208VAC (+10% / -10%), Three Phase, 50 Amp a 4 wire connection (L1, L2, L3, Earth) 60 Hz
- System electrical requirements will vary, based on the application. Peripheral equipment requires additional receptacles at the installation site (120 V, 60 Hz, 20A)
- Customer supplying main circuit breaker shall have surge protection rated for motor loads and typically at least 10 times the rated current of the machine (50 amps).

Supplied Power Plug for 4 wire Delta:

- NEMA 15-50P (Hubbell 8451C or equivalent),
- requires a NEMA 15-50R receptacle (Hubbell 8450A or equivalent)

Network Requirements:

Ethernet Cat5e - RJ45 Connector

MSE Air Requirements:

4.25 CFM @ 70 psi
5 Microns Particulate Filtration required